

Why GD&T?

- Ensures interchangeability of parts during mating / assembly
- Saves money by avoiding unnecessary overtolerancing
- Avoids (legal, machining, inspection) ambiguity
- Contributes to functional gauging of surfaces and features by establishing datums of importance
- Influences order of manufacturing steps

ASME Y14.5M



Dimensions



Dimensions





- ϕ 1.50 MIN

Useful for defining min. dimensions when max. would not interfere with feature / part utility



Feature Control Frame



Geometric Control Symbols

_				Basic	Feature	Datum
Type	Geometric Characteristics		Pertains To	Dimensions	Modifier	Modifier
Form	—	Straightness	ONLY individual feature		Modifier not applicable	NO datum
	Ο	Circularity				
	\square	Flatness				
	10/	Cylindricity				
Profile	$\left(\right)$	Profile (Line)	Individual or related	Yes if		RFS implied unless MMC or LMC is stated
	\bigcirc	Profile (Surface)		related		
ntation	$\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ $	Angularity	ALWAYS related fea- ture(s)	Yes	RFS implied unless MMC or LMC is stated	
		Perpendicularity				
Orie	//	Parallelism				
Location	Φ	Position		Yes		
	\odot	Concentricity				
	-	Symmetry				
out	ø	Circular Runout			Only RFS	Only RFS
Run	Ľ	Total Runout				

Adapted from Oberg's Machinary Handbook

Establishing Datums



Establishing Datums



Right Angle Plate



Coordinate Measuring Machines (CMMS)



Form (Straightness, —)



Lower parallel plane

All points that lie between two lines (upper and lower boundary) when measuring a line profile

Form (Circularity, \bigcirc)

All points of a plane perpendicular to a common axis are equidistant from that axis



Form (Cylindricity, /\/)

All points of the surface of a surface of revolution are equidistant from a common axis



Form (Flatness, \Box)

The distance between all elements in one plane when measured with reference to a reference plane



Profile (Line, \bigcirc or Surface, \bigcirc)

This distance between all points of a line profile or surface profile between two surfaces of the shape of the idealized surface



Orientation (Angularity, \angle)

The tolerance zone defined by two parallel planes or a cylinder at a specified angle from the datum plane



Orientation (Perpendicularity, \perp)

The tolerance zone of two parallel plates perpendicular to a datum within which a feature must lie



Orientation (Parallelism, //)

The tolerance zone of two parallel plates parallel to a datum within which a feature must lie



Location (Position, \oplus)

The exact location of a point, line, or surface in relation to another datum



Location (Concentricity, ())

The position of an axis in relation to another datum axis



Runout (Circular, /, and Total, //)

The deviation of the profile of an axisymmetric feature from a control (datum) axis



Turning

Lathe Terminology



Workholding (Collets)



Collets are located in the drawer in (or next to) the lathe

Collets sizes are selected based on the stock size



Workholding (3- and 4-Jaw Chucks)



3-Jaw Chucks

- Self-centering and quick clamping
- Cannot hold irregularly shaped work pieces

4-Jaw Chucks

- Admits square stock
- Off-center turning
- Mounting subject to eccentricities



Workholding (Tailstock)

The tailstock is used to hold the workpiece with a guide or to drill holes

Tooling



Facing/turning (carbide insert)

Part-off tool

Tool Post

The tool post connects the tool holder (tool) to the carriage

Turning Operations



Turning Operations



Turning Operations



Feeds and Speeds

Speed Equation for the Mill



Feeds and Speeds



Feeds and Speeds



Cutting Slots with the Mill

High speed steel slitting saws

Slow speed (300 – 500 RPM)
Conventional milling (avoid pulling at workpiece)